FIGURE LISTS

Figure I. 1.	Existing device in BBK	20
Figure I. 2	Ceramic tile device .	21
Figure II. 1	(a) Darker parrot image, (b) Enhanced parrot image in contrast	26
Figure II. 2	Digital image coordinate	27
Figure II. 3	Digital Image Representation in 2D	28
Figure II. 4	Binary image	29
Figure II. 5	Grayscale image	29
Figure II. 6	8 bit color image	30
Figure II. 7	16 bit color image	30
Figure II. 8	Convolution process of image example	32
Figure II. 9	Edge detection result image.	33
Figure II. 10	3x3 Pixel array around pixel (x,y)	34
Figure II. 11	Image result from edge detection with Sobel Operator.	34
Figure II. 12	Harris Corner detection result on checkboard image	36
Figure II. 13	The elements of Automation System	38
Figure II. 14	Close Loop System	39
Figure II. 15	Open Loop System	39
Figure II. 16	Examples of sensors which are used in Indsutrial Sector	40
Figure II. 17	PLC (Programmable Logic Controller).	40
Figure II. 18	HMI system in SCADA.	41
Figure III. 1	Conceptual Model Research	42
Figure III. 2.	Systematic Research Diagram	46
Figure IV. 1	Existing measurement instrument in BBK	47
Figure IV. 2	Examples of malt that used in BBK	48
Figure IV. 3	Existing steps in measuring rectangularity in BBK	49
Figure IV. 4	The Instalation process of malt on Instrument done by the operator.	50

Figure IV. 5	Operator must to made sure that the corner of the malt is installed properly on the right place.	50
Figure IV. 6	The dials was placed according to it's measurement function	51
Figure IV. 7	The value of the dial was set into 0 value.	51
Figure IV. 8	The sample tile ready to measure	52
Figure IV. 9	The Position of dials based on SNI ISO 10545-2-2010.	52
Figure IV. 10	Improvement system design	55
Figure IV. 11	Process Scenario flow (Part 1)	56
Figure IV. 12	Process scenario flow (Part 2)	57
Figure IV. 13	Process scenario flow (Part 3)	58
Figure IV. 14	Hardware and Software requirements.	60
Figure IV. 15	GUIDE Quick Start window	64
Figure IV. 16	Blank GUI workspace window	64
Figure IV. 17	Main menu display for processing the sample image.	65
Figure IV. 18	Search image program script	65
Figure IV. 19	Load image program script	66
Figure IV. 20	Start webcam program script	66
Figure IV. 21	RGB to Grayscale conversion program script	67
Figure IV. 22	Sobel edge detection program script	68
Figure IV. 23	Averaging filter program script	68
Figure IV. 24	Harris corner detection program script	69
Figure IV. 25	Quadran classification program script	70
Figure IV. 26	Carisisi program script	71
Figure IV. 27	Carisudut Program script	71
Figure IV. 28.	Hitung simpang Program Script	72
Figure IV. 29	Login display	73
Figure IV. 30	Main page for Monitoring in HMI	74
Figure IV. 31	Excel databse display	75
Figure IV. 32	Rig Improvement system design	75
Figure V. 1	Intensity histogram with standard conversion value.	80

Figure V. 2	Intensity histogram with same conversion value	81
Figure V. 3	Intensity histogram with custom conversion value.	81
Figure V. 4	Matrix image example for every layers.	81
Figure V. 5	Image without averaging filter (b)Image with averaging filter	83
Figure V. 6	Filter 7x7 with 0,84089642 sigma value	85
Figure V. 7	Before distinguish process (b) After distinguished	92
Figure V. 8	Corner determination result	93
Figure V. 9	Side length calculation results.	94
Figure V. 10	Deviation meaasurement in ISO 10545-2-2010	96
Figure V. 11	Dial placement based on ISO 10545-2-2010	96
Figure V. 12	Low lux intensity corner detection result	102

\