

## DAFTAR GAMBAR

Gambar I.1 Data <i>unexpected shutdown</i> pabrik Urea Kaltim-3 .....	2
Gambar II.1 Klasifikasi Tipe <i>Maintenance</i> .....	6
Gambar II.2 <i>Reliability Bath Tub Curve</i> .....	9
Gambar II.3 <i>Time Breakdown Scheme</i> .....	14
Gambar II.4 Tujuh tahapan metode RCM .....	17
Gambar II.5 Contoh <i>Asset block diagram</i> (ABD).....	19
Gambar II.6 Contoh <i>Functional block diagram</i> (FBD).....	19
Gambar II.7 P-F Interval.....	25
Gambar II.8 <i>Example Task Matrix</i> .....	29
Gambar III.1 Model Konseptual.....	32
Gambar III.2 Sistematika Penyelesaian Masalah .....	35
Gambar III.3 Sistematika Penyelesaian Masalah (lanjutan) .....	36
Gambar IV.1 Contoh FMEA.....	48
Gambar IV.2 Contoh <i>Decision Sheet</i> .....	48