

DAFTAR ISI

LEMBAR PENGESAHAN.....	i
LEMBAR PERNYATAAN ORISINALITAS.....	ii
ABSTRAK	iii
ABSTRACT	iv
KATA PENGANTAR	v
UCAPAN TERIMA KASIH.....	vi
DAFTAR ISI	viii
DAFTAR GAMBAR	x
DAFTAR TABEL	xii
BAB I	1
1.1 Latar Belakang Masalah.....	1
1.2 Rumusan Masalah.....	2
1.3 Tujuan dan Manfaat.....	3
1.4 Batasan Masalah	3
1.5 Metode Penelitian.....	4
1.6 Sistematika Penulisan	4
BAB II.....	6
2.1 Banjir.....	6
2.2 Mikrokontroller	8
2.3 Sensor Ultrasonik	11
2.4 Wireless.....	12
2.5 Internet of Things (IoT)	13
2.6 Quality of Service (QoS).....	15
BAB III.....	16

3.1	Desain Sistem	16
3.1.1	Diagram Blok	16
3.1.2	Fungsi dan Fitur.....	19
3.2	Desain Perangkat Keras	20
3.3	Spesifikasi Komponen	21
3.3.1	Board Arduino Mega 2560.....	21
3.3.2	Sensor Ultrasonik HC SR04.....	23
3.3.3	Modul ESP 8266-01	24
3.3.4	Modul Real Time Clock (RTC).....	26
3.4	Desain Perangkat Lunak	26
BAB IV	30
4.1	Pengujian dan Analisis Sistem Komunikasi Serial Modul ESP8266-01	30
4.2	Pengujian dan Analisis Pengiriman Data <i>Blynk</i> ke <i>Twitter</i>	32
4.2.1.	Pengujian <i>Delay Twitter</i>	33
4.2.2.	Pengujian Packet Loss	40
4.3	Pengujian dan Analisis Kondisi Sistem Peringatan Dini Banjir	46
4.3.1	Pengujian Sistem Monitoring Peringatan Dini Banjir IoT <i>Blynk</i> Level Status Aman.....	49
4.3.2	Pengujian Sistem Monitoring Peringatan Dini Banjir IoT <i>Blynk</i> Level Status Siaga.....	51
4.3.3	Pengujian Sistem Monitoring Peringatan Dini Banjir IoT <i>Blynk</i> Level Status Bahaya.....	53
BAB V	56
5.1.	Kesimpulan.....	56
5.2.	Saran	56
DAFTAR PUSTAKA	58