

## DAFTAR GAMBAR

Gambar I.1 Grafik persentase jumlah produk <i>defect</i> .....	5
Gambar I.2 Aliran proses produksi kemeja PDL .....	8
Gambar I.3 Grafik frekuensi kemunculan jenis <i>defect</i> .....	9
Gambar I.4 <i>Fishbone diagram</i> .....	10
Gambar II.1 Contoh Critical to Quality (CTQ).....	17
Gambar II.2 Tahapan DMAIC .....	19
Gambar II.3 Contoh stabilitas proses .....	24
Gambar II.4 Contoh <i>fishbone diagram</i> .....	28
Gambar II.5 Contoh SIPOC diagram .....	29
Gambar II.6 Contoh FMEA .....	33
Gambar II. 7 Contoh Analisis 5 <i>Why's</i> .....	35
Gambar II.8 Tahapan proses pengembangan produk.....	38
Gambar II.9 <i>House of Quality</i> (HOQ).....	40
Gambar II.10 Langkah-langkah HOQ.....	41
Gambar II.11 Contoh HOQ.....	44
Gambar III. 1 Sistematika Perancangan.....	49
Gambar IV.1 Objek penelitian .....	55
Gambar IV. 2 Mesin <i>Cutting Octa RS 100</i> .....	57
Gambar IV. 3 Matriks <i>Klein Grid</i> .....	63
Gambar IV. 4 Hasil matriks korelasi persyaratan teknis.....	67
Gambar IV. 5 <i>House of Quality</i> (HOQ).....	68
Gambar IV. 6 Referensi lampu sensor .....	71
Gambar IV. 7 Desain rancangan alat bantu usulan <i>autolamp</i> .....	75
Gambar IV. 8 <i>Flowchart</i> cara kerja alat bantu usulan .....	76