

LIST OF TABLES

CHAPTER 2. SATELLITE COMMUNICATION SYSTEM

2.1. Simulation Parameters from Maruddani et. al.	8
2.2. Adaptations of M-ary PSK Modulation Schemes	10
2.3. Typical Values of Decoding Gain	17
2.4. Impact of Coding for Variable Bandwidth with Object BER = 10^{-6} , BPSK Modulation	18
2.5. Impact of Coding for Constant Bandwidth with Object BER = 10^{-6}	19

CHAPTER 3. FORMULATION AND MODELLING PROPOSED ADAPTIVE CODING AND MODULATION

3.1. Data Needed for the Research	29
3.2. The Satellite Parameters Assumptions	30
3.3. The Gateway and End-user Terminal Technical Parameters	32
3.4. The Rain Rate in a Month for Cities Used for Link Budget Simulation	33
3.5. Link Budget Scenario	37

CHAPTER 4. PRESENTATION, ANALYSIS AND INTERPRETATION OF DATA

4.1. Gateway _{MEDAN} Technical Parameters	46
4.2. End-user Terminal _{PADANG} Technical Parameters	48
4.3. Medan-Padang Link Budget Result for Every Rain Rate Condition	50
4.4. Result For Clear Sky Condition in both Medan and Padang	52
4.5. Result For Rain (5.4 mm/hr) in Medan and Clear Sky in Padang	53
4.6. Result For Rain (31 mm/hr) in Medan and Clear Sky in Padang	54
4.7. Result For Rain (64 mm/hr) in Medan and Clear Sky in Padang	55
4.8. Result For Clear Sky in Medan and Rain (28.6 mm/hr) Padang	56
4.9. Result For Clear Sky in Medan and Rain (57 mm/hr) in Padang	57
4.10. Result For Rain 5.4 mm/hr Condition in both Medan and Padang	59
4.11. Result For Rain 28.6 mm/hr Condition in both Medan and Padang	60
4.12. The ModCod Threshold Determination Located in The Same Beam Coverage	61
4.13. Gateway _{MAKASAR} Technical Parameters	62
4.14. End-user Terminal _{SORONG} Technical Parameters	63
4.15. Makasar-Sorong Link Budget Result for Every Rain Rate Condition	65

4.16. Result For Clear Sky Condition in both Makasar and Sorong	67
4.17. Result For Rain (0.4 mm/hr) in Makasar and Clear Sky in Sorong	69
4.18. Result For Rain (37 mm/hr) in Makasar and Clear Sky in Sorong	70
4.19. Result For Rain (151 mm/hr) in Makasar and Clear Sky in Sorong	71
4.20. Result For Clear Sky in Makasar and Rain (5.6 mm/hr) in Sorong	72
4.21. Result For Clear Sky in Makasar and Rain (44 mm/hr) in Sorong	73
4.22. Result For Clear Sky in Makasar and Rain (228 mm/hr) in Sorong	74
4.23. Result For Rain 5.6 mm/hr Condition in both Makasar and Sorong	75
4.24. Result For Rain Rate 37 mm/hr in both Makasar and Sorong	76
4.25. The ModCod Threshold Determination for Gateway and End-user Located in the Same Beam	77
4.26. Gateway _{DENPASAR} Technical Parameters	78
4.27. End-user Terminal _{MATARAM} Technical Parameters	80
4.28. Denpasar-Mataram Link Budget Result for Every Rain Rate Condition	81
4.29. Result For Clear Sky Condition in both Denpasar and Mataram	84
4.30. Result For Rain (0.5 mm/hr) in Denpasar and Clear Sky in Mataram	85
4.31. Result For Rain (20 mm/hr) in Denpasar and Clear Sky in Mataram	86
4.32. Result For Rain (102 mm/hr) in Denpasar and Clear Sky in Makasar	87
4.33. Result For Clear Sky in Denpasar and Rain (0.01 mm/hr) in Mataram	88
4.34. Result For Clear Sky in Denpasar and Rain (17 mm/hr) in Mataram	89
4.35. Result For Clear Sky in Denpasar and Rain (109 mm/hr) in Mataram	90
4.36. Result For Rain 0.5 mm/hr Condition in both Denpasar and Mataram	91
4.37. Result For Rain 20 mm/hr Condition in both Denpasar and Mataram	92
4.38. The ModCod Threshold Determination for Favorable Condition	93
4.39. The Comparison of Threshold Determination	95
4.40. Fix Threshold Determination	96