LIST OF IMAGES

Figure I.1 Defect Escalation graphic From Collecting Area to PT. Abo Farm	
(Period 2012)	2
Figure I.2 The Factors That Cause The Occurence of Reject	3
Figure II.1 DMAIC Cycle	1
Figure II.2 SIPOC Diagram	9
Figure II.3 Cause and Effect Diagram (Ishikawa Diagram)	0
Figure III.2 Systematics Problem Solving	5
Figure IV.1 Business Process in Farmer-PT.Abo Farm- Exporters4	7
Figure IV.2 Image Process Happens in Gatherer4	8
Figure IV.3 Pareto Diagram for Types of Defect of Beans	1
Figure IV.5 Control P- Chart for Bean's Product	7
Figure IV.6 Sigma Calculator's Display for January5	8
Figure IV.7 Sigma Level Graphs5	9
Figure IV.8 Pareto Diagram for Broken Beans Types of Defect6	1
Figure IV.9 Fishbone Cause Defects Beans Parts Steam Torn Man Power Factor (1) 62	
Figure IV.10 Fishbone Cause Defect No Short-Sighted in Beans Man Power Factor 65	
Figure IV.11 Fishbone Chart of Disability Existence Nails Scratches on Bean's Surface Man Power Factor (1)	7
Figure IV.12 Ideal Conditions Lifting According to NIOSH	2
Figure IV.13 Ideal Conditions (Continued) What Should Filled According to NIOSH 82	
Figure IV.14 Aid Proposed Mechanical Equipment (Hand Truck)8	4
Figure IV.15 Form Load Beams with Handle	6
Figure IV.16 Lifting Instruction Display by Using A Form Load Beams With Handle 87	
Figure IV 17 The Load Beams Without Handle 8	R

Figure IV.18 Lifting Instruction Display by Using a Form Load Beams With Handle 89	iout
Figure IV.19 Expense Form Sack	90
Figure IV.20 Lifting Instruction Display By Using a Form of Sacks	91
Figure IV.21 The Sample Of Desks Or Sustainer Which Has A Height	92
Figure IV.22 Lifting Instruction Display For All Kinds and Shape Which Ha Height Above The Table	
Figure IV.23 Proposed Picking Process Display	102
Figure V.1 SWOT Analysis for Alternative 4	107
Figure V.2 SWOT Analysis for Alternative 1	111
Figure V.3 SWOT Analysis for Alternative	114
Figure V.4 SWOT Analysis for Alternative 2	119