

## DAFTAR SIMBOL SINGKATAN DAN LAMBANG

Daftar Simbol	Deskripsi	Halaman pertama kali digunakan
PT	Perseroan Terbatas	1
CTQ	<i>Critical to Quality</i>	1
BTP	<i>Back Top Plate</i>	1
<i>Pcs</i>	<i>Pieces</i>	3
DMAIC	<i>Define, Measure, Analyze, Improve, Control</i>	6
CL	<i>Center Line</i>	17
UCL	<i>Upper Control Limit</i>	8
LCL	<i>Lower Control Limit</i>	8
Kg/cm <sup>2</sup>	Kilogram per sentimeter persegi	60
S/N Ratio	<i>Signal-to-noise Ratio</i>	26
5W + 1 H	<i>5 What + 1 How</i>	58
cm	Sentimeter	2
P	Panjang	70
L	Lebar	70
T	Tinggi	70
<i>P</i>	Proporsi kesalahan dalam setiap sampel	18
<i>x</i>	Banyaknya produk yang salah dalam setiap sampel	18
<i>n</i>	Banyaknya sampel yang diambil dalam inspeksi	18

$\bar{p}$	Garis pusat peta pengendali proporsi kesalahan	18
$p_i$	Proporsi kesalahan setiap sampel atau sub kelompok dalam setiap observasi	18
$g$	Banyaknya sampel yang diambil setiap kali observasi	18
DPU	<i>Defect Per Unit</i>	19
DPO	<i>Defect Per Opportunity</i>	19
DPMO	<i>Defect Per Million Opportunities</i>	8
QC	<i>Quality Control</i>	77
FMEA	<i>Failure Mode and Effect Analysis</i>	21
RPN	<i>Risk Priority Number</i>	24