

DAFTAR SIMBOL

Simbol	Nama	Satuan	Halaman Pertama Muncul
A	Amplitudo	μm	7
f	Frekuensi	kHz	
fr	<i>Feed Rate</i>	mm/rev	7
h	<i>Depth of Cut</i>	mm	7
h_{min}	MUCT	mm	1
	Ketebalan	mm	
h_s	material <i>spring back</i>		7
n	<i>Spindle Speed</i>	<i>rotation per minute (rpm)</i>	15
Ra	<i>Average Roughness</i>	μm	10
r_n	<i>Nose Radius</i>	mm	1
α	<i>Rake Angels</i>	$^{\circ}$	7