

DAFTAR GAMBAR

Gambar 2.1 Arsitektur Jaringan 3G	6
Gambar 2.2 Mekanisme <i>Mechanical Tilting</i>	16
Gambar 2.3 Arah Pancar <i>Mechanical Tilting</i>	16
Gambar 2.4 Mekanisme <i>Electrical Tilting</i>	16
Gambar 2.5 Arah Pancar <i>Electrical Tilting</i>	16
Gambar 2.6 Perhitungan jarak dan sudut <i>Mechanical Tilting</i>	17
Gambar 3.1 Diagram Alir Pengukuran.....	18
Gambar 3.2 Penentuan Rute di Google Earth.....	19
Gambar 3.3 Alir Proses <i>Drive test</i>	20
Gambar 3.4 Hasil <i>Drive RSCP</i>	21
Gambar 3.5 Hasil <i>Drive Test Ec/No</i>	21
Gambar 3.6 Hasil <i>Drive Test SQI dan RLC DL Troughput</i>	22
Gambar 4.1 Diagram Alir Optimasi	26
Gambar 4.2 <i>Spot Bad Coverage</i>	28
Gambar 4.3 <i>Serving Site</i> di area <i>Bad Coverage</i>	29
Gambar 4.4 Simulasi pada <i>Kathrein site 091608_Rajadalam_3G</i>	31
Gambar 4.5 <i>Blocking Building</i> penyebab <i>Bad Coverage</i>	32
Gambar 4.6 <i>Serving Site 094386_Taman_Gandaria_3G</i>	32
Gambar 4.7 Kondisi <i>Blocking Countour site 094386_Taman_Gandaria_3G</i>	33
Gambar 4.8 Simulasi Pada <i>Kathrein site 094386_Taman_Gandaria_3G</i>	35
Gambar 4.9 <i>Bad Quality</i>	36
Gambar 4.10 <i>Spot Bad Quality 1</i>	37
Gambar 4.11 <i>serving site Bad Quality 1</i>	37
Gambar 4.12 Simulasi pada <i>Katherin site 94221_Pusdiklat_RRI_3G</i>	39
Gambar 4.13 Perbandingan Simulasi <i>RSCP Before dan After Bad Coverage</i>	41
Gambar 4.14 Perbandingan Simulasi <i>Ec/No before dan after Bad Quality 1</i>	42
Gambar 4.15 <i>Spot Blocked Call</i>	43
Gambar 4.16 <i>Event Blocked Call dan Serving site</i>	44
Gambar 4.17 Simulasi pada <i>Katherin site 094700_Radio_Dalam_3G</i>	46
Gambar 4.18 Perbandingan simulasi <i>Ec/No Before dan After Blocked Call</i>	47
Gambar 4.19 <i>Low RLC DL Througput</i>	49
Gambar 4.20 <i>RSCP dan Ec/No Data</i>	50
Gambar 4.21 Perbandingan Simulasi <i>RSCP Before dan After</i> di area Jakarta Selatan.....	42
Gambar 4.22 Perbandingan Simulasi <i>Ec/No Before dan After</i> di area Jakarta Selatan	53